



State of Utah

Department of Natural Resources

ROBERT L. MORGAN Executive Director

Division of Oil, Gas & Mining

LOWELL P. BRAXTON Division Director OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE Lieutenant Governor

July 28, 2004

TO:

Minerals File

FROM:

Tom Munson, Senior Reclamation Hydrologist

SUBJECT:

Site Inspection, Bullseye #1, Ed Lister, S/023/031, Juab County,

<u>Utah</u>

Date of Inspection:

March 30, 2004

Time of Inspection:

11:20a.m.- 1:20p.m.

Conditions:

Sunny

Participants:

Tom Munson, DOGM and Ed Lister, operator

Purpose of Inspection:

To look at the mine area and determine what was disturbed.

Getting to the site:

The site is accessed by way the Delta Power Plant Highway to Brush Resources, but turning towards the town of Joy.

Observations:

The disturbance at the site was not much different then previous inspections. Ed and I walked the two pits on the North and South side of the knoll. I GPS'ed the pits and the access roads going to and coming from the site.

Conclusions and Recommendations:

The BLM has a \$5,100 bond for the site and I see no reason that this would not be adequate to reclaim the site.


TM:ib


Attachment: Photos cc: Sherri Wysong, BLM

O:\M023-Juab\S023031-Bullseye\inspections\03302004insp.doc

CC: Ed Lister








P0005050.JPG Unknown


NORTHERN DIT

BULEYE # 1 SITE INSPECTION OATE: 3/30/2004


ton mensor




BULLSEYE1.JPG



P0005047.JPG Unknown





P0005048.JPG Unknown